arranty Issue				latest version of the guide: www.scottoiler.com/support_fitting.asp	helow:	
	Fitting a Scottoiler may invalidate the Triumph warran	ty on your bik			Delow:	
				(To get an installation guide for your make and model of bike go to the following we	h nage -	
ystem / Unive		not	suitable with	www.scottoiler.com/support_installation-guides.asp)	product	cost o
manufacturer	model	suitable	adapters / mods	adapters / modifications / reasons	code	adapte
Aprilia	Capo Nord, Futura		X	Tee Connector - 6mm	RM-150250	FOC
	RXV & SXV 45 & 55 SL 750 Shiver	x	x	Tee Connector Triumph - 8mm	RM-150245	FUC
	Pegaso Fi 2000		x	Universal Spigot (required for vSystem only)	SA-0095	FOC
Benelli	Tornado TRE 900		x	Tee Connector Triumph - 8mm	RM-150245	FOC
BMW	F800 GS & F650 GS (800cc) (08-)		x	Model specific kit available from dealers	SO-2005	£89.9
ССМ	G650 Xchallenge, Xcountry, Xmoto & F650 GS Fi		X	Universal Spigot (required for vSystem only)	SA-0095	FOC
	404		X	Tee Connector - 6mm	RM-150250	FOC
	604E Rotax model		X	Universal Spigot (required for vSystem only)	SA-0095	FOC
Ducati	Monster S4R (04-06), S2R (05-07) & S4R Testastretta		X	Front Sprocket Feed necessary, Adapter Kit available soon	TBC	TBC
Honda	CB1300 Fi		x	Single Sided Swing Arm adapter	SA-0090	FOC
	XR250/400/600R, XBR500, SLR650, Rebel CMX250C		x	Universal Spigot (required for vSystem only)	SA-0095	FOC
	1000S, 1000SF & 1000ST		x	Universal Spigot (required for vSystem only)	SA-0095	FOC
Suzuki	Bandit 1200, Bandit 600 (00-04), GSX600F, 750&SV650 Carb 99-02		x	Tee Connector - 6mm	RM-150250	FOC
	DR350		x	Universal Spigot (required for vSystem only)	SA-0095	FOC
Triumph	All Triumph fuel-injected models after 1997 with 955cc		x	Tee Connector with Viton Triumph - 8mm	SA-0155	FOC
	engines Tiger 885cc (99 & 00)					
	T509 Speed Triple (pre 1997), T595I		X	Tee Connector Triumph - 8mm	RM-150245	FOC
	Speed Four, TT600 Tiger {955cc} (from 2000)		x	Tee Connector with Viton Triumph - 8mm	SA-0155	FOC
Yamaha	RD250LC, RD350LC 1981 & DT125		x	Universal Spigot (required for vSystem only)	SA-0095	FOC
al Injector						
manufacturer	model	not	suitable with	adapters / modifications / reasons	product	cost c
Aprilia	Futura, RSV Mille 04 on, RXV45&55, Tuono 06 on	suitable X	adapters / mods	Unsuitable swinging arm	code	adapte
BMW	Xchallenge, Xcountry & Xmoto	^	x	Chain guard must be removed if fitting Dual Injector		
Cagiva	Raptor & V-Raptor	x		Unsuitable swinging arm		
CCM	404	x		Unsuitable swinging arm		
Ducati	749 & 999 (pre 06) Multistrada 1000DS / 1100DS		x	Requires drilling the swing arm		
	GT1000, Paul Smart 1000 LE&Sport 1000, Monster S2R					
	800(05-07) 1000(06-), S4R 996cc(04-06) S4RS&S4RS Testastressa 998cc(06-)	x		Unsuitable swinging arm		
Honda	CG 125, CB400T	x		Unsuitable swinging arm		
	VFR750, Bros USA Hawk	^	x	Dual Injector VFR750 Adapter Kit	SA-0094	FOC
	VFR800i		x	Dual Injector VFR800i Adapter Kit	SA-0092	FOC
	VFR800 VTec	x	~	Poor clearance between sprocket bolts and swinging arm	0,10002	
Kawasaki	125 Eliminator, W650, ZZR1400	x		Unsuitable swinging arm		
Triumph	Bonneville, Thruxton, Scrambler (Pre 08)	x		Unsuitable swinging arm		
Yamaha	600 Diversion, MT03, FZ1, RD250&350LC (1981)	x		Unsuitable swinging arm		
	lagnum HCR		suitable with	SCOTTOILER LUBE TUBE instead - the flexible 200ml alternative to	-	
manufacturer	model	not suitable	adapters / mods	adapters / modifications / reasons	product code	cost c adapte
	It is also worth noting that the installation of the In both of these cas	e Magnum HCF es we would re	R pushes the rear r ecommend fitting a	is the rear mudguard may not be rigid enough for the weight of a full Magu number plate back by 45mm which may obscure the number plate light on Sottolier Lube Tube to give extra on-board oil capacity. <b>Sottolier Lube Tube to give extra on-board oil capacity.</b>		
Aprilia	Capo Nord, Falco, Futura & SXV	x		Rear mudguard unsuitable + pipes at risk from exhaust		
BMW	FS650GS & Dakar without panniers, Xchallenge, Xcountry & Xmoto	′ <b>x</b>		Rear mudguard unsuitable for weight of HCR		
Ducati	Multistrada & ST4S, Monster S2R 800(05-07) 1000(06-), S4R 996cc(04-06) S4RS&S4RS Testastressa 998cc(06-)	x		Rear mudguard unsuitable and obscures number plate light		
Honda	Blackbird		x	Must be lowered to clear seat keyhole	SA-0072	FOC
	CB1000, 1300, X4 1300 & CB1300 Fi CBF1000 (06-)	x		Obscures number plate light		
	CG125, Hornet 600 & VFR800Vtec	x		Rear mudguard unsuitable for weight of HCR		
Kawasaki	125 Eliminator, ER6, W650, Z750 (2007), Z1000 (2003-06), ZZR1200&1400, ZX12R & KLE500	x		Rear mudguard unsuitable		
	KLV1000	x		Obscures number plate light		
KTM	990 Adventure	x		Obscures number plate light		
MZ Suzuki	1000 S, 1000 SF & 1000 ST	x		Rear mudguard unsuitable for weight of HCR		
	DL650 & DL1000	x		Obscures number plate light		
Triumph	SV650 & SV1000 (2003-) & DRZ400	×		Rear subframe lugs / mudguard unsuitable for weight of HCR		
I riumph	Daytona 675, Tiger (1050cc)	x		Rear mudguard unsuitable for weight of HCR		
	Speed Triple, Street Triple & Sprint ST (1050cc)	X		Rear mudguard unsuitable + pipes at risk from exhaust		
	Sprint, Sprint ST & Tiger (955cc), Bonneville, America, Speed Master & Thruxton	x		Obscures number plate light		
Yamaha	Sprint, Sprint ST & Tiger (955cc), Bonneville, America, Speed Master & Thruxton	x x	x	Obscures number plate light Obscures number plate light HCR Mudguard Adapter Kit	SA-0072	FOC